



PO Box 1150
Issaquah, WA 98027
(206) 965-5797

J. Jeffrey Huber Daily Report

9/25/20

River inspection – 0630 (Corey A. Crew) a crew of 5 person started at the intake and walked downstream 1.5 miles and surveyed for any debris. Small pieces of the turf were found and recovered. Crew recovered trash that was found on the bank as well. Trash was not organic to the project.

Construction – Crews started to drive sheet piles so they can begin excavating the center abutment. Crews continued to work on dewatering. Crew cleaned and unplugged pipe for water supply. Crews have been moving spoils to proper dumpsite onsite since 1130.

JH – 1400 Excavator blew a hose and leaked organic based hydraulic oil. 8 crew plus JH & managers responded. Crew was on it by the time I got there. They all diapers and booms laid out and were collecting the soiled diapers and putting them into plastic garbage bags. Crew was still cleaning ground with diapers at 1600. None of the hydraulic oil reached the river.

JH – Water quality monitoring went as per plan

JH – Fish Biologist in place to observe fish ladder.

Sincerely,

J. Jeffrey Huber
Encore Environmental
Representing Electron Hydro